

HIGHWAYS REPORT - Fault Inventory May 2021 Blue shows progress during the last month and red for several months

LOCATION	Postcode	Fault	Reference	CCC Status	Notes
Near Castle View		Pothole	W1980984248	Future Work	Submitted 2019
Raines Hall Farm		Pothole	W1980984249	Future Work	Submitted 2019
Pavements between aqueduct and Sedgwick House		Manhole cover Pavements defect	W1980956164 W1980956165 W1980956166	Further Assessment	Submitted BH February 2019 after 2 residents complained – update March 2019 assigned for future work Technical Team to investigate in next 4 weeks
Castle View Pavement	LA8 0JL	Repair all pavements	W1980958222	Further Assessment	Re-submitted March 2019 BH/ Technical Team to investigate in next 4 weeks
Sign – Wellheads Lane		Better position	W1880931996	Problem logged 27 Nov 2018	Enquiry Complete V Upton/CRASH Committee /PC Jackson work scheduled to add extra sign on north side of aqueduct Jan 2021
Junction Carex Farm Junction Aqueduct/Back Lane		No Slow Sign No Slow Sign	W1980977462 W1980977463	Problem Logged Problem Logged	Submitted September 2019 Submitted September 2019 CRASH committee/PC Jackson investigating signage and road markings to improve safety Jan 2021
Back Lane J by Aqueduct		pothole	W2081002813	Problem logged	Future Work
Back Lane Speeding Traffic		Speed of Traffic	W2081016228	Problem logged 15 October 2020	Enquiry Complete V Upton investigating signage for pedestrian crossing Request for consideration for 20mph speed limit refused - CRASH Committee Jan 2021 Cyclist safety signage to be installed Jan 2021 - CRASH Committee/PC Jackson-
Nanny Pie Lane from Brettaghtholt Roundabout		Sign to Sedgwick Hit	W2081013571	Problem Logged	Submitted 14/9/2020- problem Logged

Request litter bin by Millennium Field and River Kent by grit bin			1068701 SLDC	Logged 17/2/21 Locality team	Cost Sue Warner 17/3/21 Cllr Tanham – contact Sion Thomas -funding app
Damaged Grit Bin by River Kent			W2181039070	Logged 18/3/21	Problem logged

Updated 30th April 2021 – S Roberts