

HIGHWAYS REPORT

Fault Inventory April 10th 2018 (AA= Awaiting Assessment) Red shows progress during the last month

LOCATION	Postcode	Fault	Reference	Logged*	CCC Status March	CCC Status April	Notes
Basinghyll Gulley	LA88ED	Blocked Gulley Again	W1880915785	5/2/18	AA	AA	Still flooding road
Riverside to Force Bridge	LA80JU	Erosion of edge near bend Multiple Potholes/resurface	W171439589 W171447978 W1880915423 W182936296 W1880915422 W18809183608 W1880923112 W1880926088	13/06/2017 21/09/17 02/02/18 02/02/18 02/02/18 19/02/18 12/3/18 31/3/18	Completed Completed AA AA AA AA AA	Removed Removed AA AA AA AA AA	Never done Never done Verge and potholes all deteriorating. Cars grounding on verge collapse caused by Storm Desmond in Dec 2016
Castle View Junction	LA80JL	Renew Road Markings	W171439590	13/06/2017	Completed		ALL COMPLETED April 2018
Wakefield Meadow Junction	LA80JD	Renew Road Markings	W171439600 W182936237	13/06/2017 20/1/18	Completed Completed		
Carex Farm Junction	LA80JJ	Renew Road Markings			Completed		
Carex Farm to Shyreakes	LA80JJ	Potholes/edges/ resurface 2miles	W182936269 W182936266 W188096926 W1880915079	13/01/18 13/01/18 11/2/18 1/2/18	AA AA AA AA	AA AA AA Update	Carex Farm re-patched 3/1/18 and Raines Hall patched 13/1/18 Repairs failed and rereported
Castle View Pavements	LA80JL	Repair all pavements	W171439597	13/06/2017	completed	Not complet	NOT COMPLETED but removed from system
Hill Close Pavements	LA80JR	Repair all pavements	W171439592	ongoing	Due 4/18	expected 4/18	Still awaiting completion
Crosscraze Rd T J	LA80LB	Various pot holes	W171447979	21/09/2017	Completed		Large Pothole filled February 2018
Well Heads Lane (N)	LA80JS	Large deep pothole	W1880915410	2/1/18	AA	AA	ALL COMPLETED April 2018
Natland Road		Verge Collapse Pothole and white lines	W182936250 W182936251	13/1/18	AA		
Well Heads/Gypsy Hill	LA80JT	Deep Pothole	W1880915419	2/1/18	AA		
Sedgwick Hse Gateway	LA80JU	Drain Collapse	W1880915784	5/2/18	AA	Awaiting Update	
Cracked BT manhole cover at Castle View	LA80JL	Cover cracked and tripping people/dogs	W182936261	13/1/18	AA	Awaiting Update	
Sedgwick Railway Bridge	LA8 OJH	Bridge height sign loose and hanging	W182936568	13/1/18	Completed	Rereported	Re-reported Hanging off still
Cooper Hill Drain	LA80JU	Re collapse of drain	W1880925662	26/3/18		AA	
Cooper Hill Verge	LA80JU	Verge collapse	W188092608	29/3/18		AA	
Aqueduct Pavement	LA80JU	Lines/signs/road					PARTIAL completion height signage not replaced

Website Report 10/4/18

We have continued to add the final touches to the new website – all archived meeting minutes are now uploaded and current meetings are being added as appropriate. The new system of separating agenda/minutes and reports is working well and makes the transition between displaying draft and approved minutes far easier. The weather widget was discontinued has had to be replaced by treble 3 at a cost of £14 including VAT. SLDC have changed our website address on their page. The Public Statement on Potholes issued by CCC has been added.

The facebook feed on the homepage is proving very useful; the feed can easily be updated with any community messages we receive and this is happening about twice a week.

Sylvia and I have been in communication with Ann regarding training and we are waiting for her to name a date. Meanwhile, the WI have asked for us to display their annual events calendar and a new page has been designed and uploaded dedicated to the WI.

Our next step is to develop a cookie policy and privacy statement and we have contacted CALC for advice. This aspect is very much related to our GDPR work which is also dependent on advice from CALC.

Boyan Holmes

Data Protection Report 10/4/18

Since our last meeting, we have registered with the ICO in accordance with The Data Protection Act 1998. A direct debit has been set up to keep this registration updated annually. We have received a 50% reduction in training costs following our complaint, which we consider fair. The CALC toolkit circulated in March has been withdrawn and will be replaced by a less complicated version as soon as possible. It is difficult to make progress towards compliancy with the GDPR until we receive this guidance. However, in the meantime, we need to ensure that our email procedures are as secure as possible.

- All councillors should be using a dedicated email address – this is for their own security in addition to being best practise. I will help set these up.
- We should be using a disclaimer footer at the end of each email. This is infuriating but necessary. It can be simply copied into your footer settings so it generates itself at the bottom of each email.
- When sending to multiple recipients, the BCC field not the CC field should be used to keep the recipients addresses secure.

Cllr Boyan Holmes

Canal Report

There is no significant change to report on canal towpath..... Spring flowers such as daffodils and celandine are in abundance but crocus are few and far between.....

Dog fouling seems to have improved but still some miscreants around.

The wall at top of easier path still awaiting repair but I think Cllr Willacy has information on this repair. Minor repairs required to finial on top of the mileage sign at aqueduct and also to place wooden lateral battens either side of the path to bottom of easier access slope which keep stones in place have been run over at some time so are now cracked.

Cllr Smith